



Lindsay Water Conditioning of Yankton, Inc.
Ecowater Systems LLC
209 E 3rd St
Yankton, SD 57078
1 (605) 665-7471
ecowater7471@live.com

The manganese and iron build up in the softeners specifically on the high school side has caused the units to lose major flow rates. The high school units are currently on bypass which means hard water is running through to everything. Our quote to eliminate this problem is to add a filter like we have at the casino (see below). We also plan to acidize all the units to clear up a lot of the buildup. The high school side we do need to rebuild unit #3 as well during this process. The elementary side of the school is starting to do the same as well, same goes for the main building (gym, kitchen, etc.). With the elementary and main part of the school we would need to acidize as well but no rebuild is needed.

