

WCHS Board of Education
Facilities Committee Meeting
September 9, 2020

1:30 PM

Washington Community High School - Admin Office

Agenda

1. Call Meeting to Order
2. Roll Call
3. Visitors and Correspondence
4. Summer Maintenance Closeout Report
5. 10-year Health/Life Safety Report
6. Facility Strategic Plan Proposal
7. Front of Torry Update
8. School Bell Update
9. Scoreboard Update
10. Other
11. Adjournment

Facilities Committee - Essig/Nofsinger/Ward

SUMMER PROJECTS	Maint Assignment	Status
Class room moves/furniture		COMPLETE
Placement of Bell @ Entrance?		IN PROGRESS
Install GFCI's per code requirement near sinks (Cory)		COMPLETE
work on deficiencies from HLS report.		COMPLETE
Change Locker combos in West Gym (Roger)		COMPLETE
Spray and clean rocks off all TPO roofs		COMPLETE
ECSI Controls for remaining 15 units		COMPLETE
Turn water on for grounds		COMPLETE
Tape off area around humidifiers in new construction		COMPLETE
Kitchen PM's		COMPLETE
Blacktop Repair		COMPLETE
Through bolts on all wood doors in need		COMPLETE
AC for pressbox (portable)		ORDERED
Put 3M strips back after custodial waxes ramps to horse shoe. Lisa orders them. If we don't wax 3M material is 1k savings		COMPLETE
Clean boilers		COMPLETE
Hose Bib on roof/ fix bad ones.		COMPLETE
Re paint parking lots and Circle drive		COMPLETE
Repair ticket booths at football. New lights/Roof		PARTIAL COMPLETION
Fix Runoff areas@Football Stadium,Court yards & Behind maint.		COMPLETE
Clean exhaust grills in entire school		COMPLETE
Clean all air returns and supply vents		COMPLETE
Take care of all landscaping and beds		COMPLETE
Trim bushes		COMPLETE
Mow and trim grounds		COMPLETE
Clean storm drains		COMPLETE
Service Door Closures		COMPLETE
Service all HVAC equipment - AHU's, RTU's, Unit Heaters		COMPLETE
Clean and repair all school lockers		COMPLETE
Change all water filters to fountains and ice machines		COMPLETE
Patch Concrete Wall on switchback behind T. Gym		COMPLETE
Touch up paint on 1st and 2nd floor		COMPLETE
Paint hand rails		PARTIAL COMPLETION
Color code padlocks for outdoor facilities		COMPLETE
Pressure wash canopy's		COMPLETE
LED lighting installation		COMPLETE
Change emergency lights/batteries.		COMPLETE
Paint rooms after smartboard insall and wire mold adjustments		COMPLETE
Old band classroom set up		COMPLETE
West Stage Curtain		COMPLETE
Ladder for new Band Bldg. roof		PLANNING
Paint Old Concession Stand - Chipping paint		INCOMPLETE
Electrical at East Platform of Stadium		COMPLETE
CONTRACTED WORK	Cost	

10 yr HLS		
Panel identification		HLS
Gym floor resurfacing	T.Gym - \$5700.00 W. Gym - \$2950.00	Allred
Tennis court repair and new net systems		

WISH LIST	Cost
Trailer/dump bed	\$5,000.00
Build storage behind shop	\$10,000.00
Grayco True liner painter	\$3,500.00
Roof over salt storage	\$5,000.00
Siding on Baseball/old Concession Stand	\$15,000.00

Future Projects	Cost
Fence around discus.	
Repair Babcook sign landscaping/Pour Pad for Panther?	
New water shed out by baseball (Dimensions and plan)	
Paint baseball Bldg and foul poles	
Paint metal pillars in the MPR	
Remove old and install new toilet partitions in the lower mens bathroom in B16 area and others in poor condition	
Paint Torry Gym Railing	
Paint interior and Ext Steel doors	

Status	Email Address	Type of Request	Work Needed	Why work is needed	Room number/location
Complete	cjwhisker@wacohi.net	Maintenance	The receptacle under my SmartBoard needs a multi-port adaptor removed and a 2-gang box and receptacles installed if possible. The box can be surface mount. If a 2-gang isn't possible then simply refurbish the existing receptacle. Everything currently plugged into the receptacle can be unplugged w/o harm.	To meet safety guidelines and to, hopefully, provide more ports.	181
In Progress	cjwhisker@wacohi.net	Maintenance	New receptacle, or two, mounted on lab wall near to the wood lathe. It is a concrete block wall. If approved I can/will provide a more precise location.	For safety and convenience. Currently extension cords must be run to tools & equipment in that location.	181 LAB
Complete	awenze@wacohi.net	Athletics	All gates in and outside of the Tennis facility need to be fixed or adjusted so that they can be properly secured/flocked.	There are several fence gates that do not close properly therefore they cannot be secured.	Tennis Courts
Complete	bmuniz@wacohi.net	Maintenance	light above teacher desk out	not sure if it is just a matter of replacing bulbs as that has been done and it goes out soon after???	150/FL hallway
Complete	tmnoe@wacohi.net	Maintenance	LL Study Hall vent above desk is very, very, noisy.	The volume of the clanging and rattling is a distraction to the students in study hall.	LL Study Hall
Future Project/Planning	cajordan@wacohi.net	Maintenance	consider adding cabinets and sink for nurse's office Bulletin board along wall with lockers is broken. There is missing pieces of the outside boarder. Can it be repaired or replaced?	Commonly need to wash hands when bathroom sink is not available. Merging most supplies to the cabinets where the sink would be located.	Nurse's Office
Complete	mwarfield@wacohi.net	Maintenance	desk in back of room 237 has rough edge, possibly missing a piece.	It is very difficult hang anything to it and requires a lot of extra time and effort to hide the back of it.	237
Complete	mwarfield@wacohi.net	Maintenance	Team room and office painted	It has snagged students and teachers clothes and scratched people walking by.	237 toward the back right side of the room
Complete	ksbarth@wacohi.net	Maintenance	Please move smart TV up about 6 inches	Paint chipping and mismatched. I can even have staff do it, if not possible for maintenance to do	Torry Gym Girls Locker room/Office
Complete	kitlakson@wacohi.net	Technology	All the Adobe Creative Suite programs need to be updated to 2020 version. I sent in an order previously but didn't know if it got updated. This should be on all computers in the art department (workstations in 168 and all teacher stations). This could be always a Christmas break item since that is when the update happens.	It's a little low and that makes it difficult for the students in the back to see the entire screen.	252
Complete	jclifford@wacohi.net	Technology	Fix raising implement on back set of blinds (string is broken)	Compatibility purposes when exchange files to different version. In order to raise blinds without having to stand on something to reach the broken string	168, 172, 173
Complete	bparrott@wacohi.net	Maintenance	Light fixture	One of the light fixtures in the room is faulty as it does not turn on at the same time or strength as others. It is the second row from the door and second row from the front of the room.	142
Complete	bparrott@wacohi.net	Maintenance	Sink and mirror removal.	It is very distracting to students and takes up space that could be used for a table/shelf to house more resources for students.	142
Complete	jkeyes-lutz@wacohi.net	Maintenance	In room 235 move calendar on wall by phone to room 253 location TBD	moving rooms	235 to 253
Complete	csteffen@wacohi.net	Maintenance	from room 235 move small dry erase board by computer to room 253 location TBD	moving rooms	235-253
Complete	csteffen@wacohi.net	Maintenance	The practice rooms in the music hallway needs sound paneling. The boosters offered to do this but Joe wanted to check things out when Ryne got back. The boosters can still do this -- but either way (school or boosters) they are really needed.	Loud noise in a cement room -- very bad on the ears. We tried to get our student recognition plaques hung up in our room. Maintenance found that doing so would cause problems for there is sand in the blocks. Joe suggested looking into a display case (that had safety glass) to put in the lobby.	Music wing.
In Progress	jalliman@wacohi.net	Maintenance	Shatterproof glass display case added to lobby outside of music wing and Dr. Freeman's office.		Lobby outside of music wing and Dr. Freeman's Office.

Status	Email Address	Type of Request	Work Needed	Why work is needed	Room number/location
Complete	ireem@wacohi.net	Maintenance	Please attach paper/form file holder to the wall next to the choir office door. (It is currently on the floor next to where it should be placed.) Please make sure when you place it that short people can reach the top forms. Thank you!	Just to finally get that thing off the floor. It screws into the wall, but the mounting hardware was lost in the move.	Choir room
Complete	ireem@wacohi.net	Maintenance	If the big wooden rolling cabinets (formerly for band) are still on the stage, I could use 3-4 of them for costume storage in the choir room. I do not need more than 4 of these cabinets.	Costume storage is always needed in the choir room. Thank you!	Choir Room
Complete	jocclifford@wacohi.net	Maintenance	Help with rearrangement of room for large furniture. We can do majority of it but will need some assistance for the larger heavier furniture.	We are getting new Smartboards in the department and the location of them will require the rest of the room to be rearranged.	Art Department (168,172,173) 249 and 251
Complete	mpacelli@wacohi.net	Technology	There was much discussion at the beginning of 2nd semester with tech department about technology and rooms 249, 251, and 253. We think there might be more drops available but just were not accessible and we did not have the time with the semester beginning. Ryan and Caleb should know what I am referring to. Anyways this is our hope and we know it might be possible.	Access to desktops if available. It makes printing much easier from staff for students...accessing grades from their assigned areas...etc.	
Complete	twalcott@wacohi.net	Maintenance	Room 249- 3 drops. Right now we have two (pacelli and arenholtz). Lifting will moving to 249 and another desktop. There is a possible drop that Ryan and Caleb found so we could have 3 access points in 249. 251. Right now we have 1 access point for a desktop. Is it possible to have 2. 253 Good!		
Complete		Maintenance	Please put some type of ventilation in student bathrooms where windows can't be opened. Something like a window fan?	Increase cleanliness, hygiene of stale air in those bathrooms.	Bathrooms without windows that can open.
In Progress	jocclifford@wacohi.net	Maintenance	Installing a Powerwasher station in Jayme's Room. Dwight Hershberger has designed plans for this to be installed in the corner by the sinks. We will upload plans when we find them (think they are at school). I do not know if he will build it or we will need Maintenance.	We all have classes that require the equipment to work on a type of art. We have been in discussion about this for the past year and this summer we would appreciate it to actually be installed.	168
Complete	jmillier@wacohi.net	Maintenance	Just wanted to place the work order for it to be done roof above fume hood in room 236 leaks and then shorts out the motor switch on the fume hood	The switch on the fume hood motor had to be replaced twice this year after the roof leaked	236
Complete	jtallman@wacohi.net	Maintenance	Filter in band room drinking fountain needs replaced.	The light is red. Chromebook carts need to be plugged in directly to an outlet, and the only one currently in the front is used completely by the smartboard and the computer. The cart can no longer be kept in the back because it will need to be shared with other teachers during the day.	Band room.
Complete	kitollakson@wacohi.net	Maintenance	Please create/run an outlet at the front of the classroom, next to the door, preferably on the side with the light switch, not the side with the chalkboard.	Chair gets stuck in the dip.	room 252
Complete	jmwood@wacohi.net	Maintenance	The tile on the floor behind my desk is starting to dip again. It was fixed once, but is starting to dip again. Since I am moving into 215/217 I would like to have the white boards from 214 move with me if there is room. When Deb Fox gets into the building site is going to check to see if there is room.	We use the white boards for scheduling everyday and I am moving rooms.	214 moving across the hall to 215/217
Complete	jmwood@wacohi.net	Maintenance	Add visio and maintenance for Football Lap tops, my school work station and Panther Plex Computers	Visio to be able to run as playbook, regular maintenance for computers	146/Panther Plex
Complete	dcrouch@wacohi.net	Technology	Playoff signs reattached to Panther Plex and Washington Panthers to Press box	Wind knocked off part of pressbox sign and Playoff signs on Panther plex	Press box / Panther plex deck
Complete	dcrouch@wacohi.net	Maintenance	Add another computer station and screen in Coaches room at Panther Plex in office nearest baseball field.	Not enough stations when coaches are working on film breakdown and	Panther Plex
Complete	dcrouch@wacohi.net	Technology			

Status	Email Address	Type of Request	Work Needed	Why work is needed	Room number/location
Complete	kortiz@wacohi.net	Maintenance	Add an outlet on the wall with the door near the front of the room or near the door. I would prefer to have an outlet by the lockers, but I can't remember if there is space to allow for that. Underneath the phone would be my second choice, and my last preference would be to the right of the door if you're inside 244. Not sure if need a ticket for this. Ordered a dry erase board for room 251. Will not be here until later in summer. Will place dry erase board on wall under red fire alarm if able. The two bulletin boards will be removed. The larger bulletin board will be placed in room 253 near the other bulletin board or centered on the wall. The smaller bulletin board will be set aside and placed somewhere at a later date. A new smartboard is supposedly being placed in 249. If this happens then can the current white board be moved to the empty wall. Not sure if this is needed as a request or not but figured better to enter both of these. Thanks!	Chrome books must be plugged into the wall. I need access to a plug near the door so that Chromebooks can be moved in and out of my classroom as they are needed for sharing among multiple teachers.	244
Complete	npacelli@wacohi.net	Maintenance		The need for a dry erase board in room 251 or the academic resource area.	251
Complete	npacelli@wacohi.net	Maintenance		A dry erase board needs to be available in the classroom for intervention resource	249
Complete	mkugler@wacohi.net	Maintenance	One of the handles came off of a window in room 240. It is currently setting on my desk. If it could be replaced or fixed, that would be great.	maintenance	240



EXECUTIVE SUMMARY

The following information and monetary values reference the 10-Year Health/Life/Safety report dated August 04, 2020, performed by Farnsworth Group, Inc. and Midwest Engineering Professionals, Inc. Please note the categories recognized by the Illinois State Board of Education (ISBE) include *Urgent*, *Required*, and *Recommended*. *Urgent* describes an issue that should be addressed within (1) year of time; *Required* describes an issue that should be addressed within (5) years of time; and *Recommended* describes an issue that should be addressed within (10) years of time.

ARCHITECTURE

Urgent:	\$56,755
Required:	\$46,493
Recommended:	\$335

PLUMBING

Urgent:	None.
Required:	\$48,800
Recommended:	None.

MECHANICAL

Urgent:	None.
Required:	\$170,100
Recommended:	\$4,021,500

ELECTRICAL

Urgent:	\$195,800
Required:	\$892,083
Recommended:	\$777,875

TOTALS

Urgent:	\$252,555
Required:	\$1,157,476
Recommended:	\$4,799,710

<u>GRAND TOTAL:</u>	<u>\$6,209,741</u>
---------------------	--------------------

Note: Items submitted to ISBE automatically include additional 10% Contingency and 10% Architectural/Engineering fees. The final number including these factors totals \$7,451,690*.

[* This total is slightly more than the number generated by the State's online submittal system, due to a special amendment requirement for some exterior work at Torry Gym totaling \$13,500. The number submitted to the State totals \$7,435,124.]

Farnsworth Group

ISBE Health Life Safety Survey Information

Washington Community HS / District 308 / Architectural

Ref. Plan Keynote	Room Name	Location	Code	Priority Code	Rule Violated	Description of Violation	Recommendation to Correct	Action ID	Specifications	Units of Measure	Quantity	Labor Code	Work Type	Estimated Cost	Estimated Completion Date {MM/DD/YYYY}	Funding Type
	GENERAL:															
	EXTERIOR:															
A13	Stairs/Sidewalk north of Torry Gym	Torry	185	Required	Exterior	Heaved concrete, cracked concrete and exposed rebar	Repair problem areas, grind down heaved tripping hazard(s)	Repair	Special Board Meeting required	ea.	1	Contractors	Safety Standards	\$13,500		Other Funds
														*		
	BASEMENT:															
A1	Locker Room B18	1942	185	Required	185.370.b.4	Floor material missing and/or in disrepair causing trip hazard	Patch hole and add floor tile to tie in with existing flooring.	Improve	Patch hole and add floor tile to tie in with existing flooring.	s.f.	20	Contractors	Safety Standards	\$450		Other Funds
A16	Old Boiler Room B22	1942	185	Required	185.390	Some hazardous/combustible material is not stored in an approved cabinet	Provide additional flammable storage cabinet	Improve	Provide additional flammable storage cabinet	ea.	1	strict Employee	Safety Standards	\$200		Fire Prevention
A2	Storage T20	Torry	185	Required	185.550	Missing electrical cover plate	Provide new cover plate	Improve	Provide new cover plate	ea.	1	strict Employee	Safety Standards	\$2		Fire Prevention
A2	Business Classroom B9	1942	185	Required	185.550	Missing electrical cover plate	Provide new cover plate	Improve	Provide new cover plate	ea.	1	strict Employee	Safety Standards	\$2		Fire Prevention
	Business B7				Tell Owner	Tornado and/or fire evacuation signage missing	Provide fire and/or tornado evacuation instructional signage							*		
	Computer Lab B12				Tell Owner	Tornado and/or fire evacuation signage missing	Provide fire and/or tornado evacuation instructional signage							*		
A2	Lounge B11	1942	185	Required	185.550	Missing electrical cover plate	Provide new cover plate	Improve	Provide new cover plate	ea.	1	strict Employee	Safety Standards	\$2		Fire Prevention
A3	Social Studies B6	1942	185	Required	185.390.g.2	Wall mounted hold open, no closer	Install new closer	Improve	Install new closer	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A3	Social Studies B5	1942	185	Required	185.390.g.2	Wall mounted hold open, no closer	Install new closer	Improve	Install new closer	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A3	Social Studies B4	1942	185	Required	185.390.g.2	Wall mounted hold open, no closer	Install new closer	Improve	Install new closer	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A4	Social Studies B1	1942	185	Required	185.390.g.2	No closer	Provide door closer	Improve	Provide door closer	ea.	1	Contractors	Safety Standards	\$310		Fire Prevention
A6	Storage T25	Torry	185	Required		No rated door	Install new rated door/hardware	Improve	Install new rated door/hardware	ea.	1	Contractors	Safety Standards	\$1,350		Fire Prevention
A7	Storage B7A	1942	185	Required	185.390.g.4	Storage Room under stairs	Install (2) 5/8" FR Gyp board on hat channels at ceiling/below stairs	Improve	Install (2) 5/8" FR Gyp board on hat channels at ceiling/below stairs	s.f.	280	Contractors	Safety Standards	\$2,270		Fire Prevention
A6	Storage B7A	1942	185	Required	185.390.g.2	No rating on door	Install new rated door/hardware	Improve	Install new rated door/hardware	ea.	1	Contractors	Safety Standards	\$1,350		Fire Prevention
A2	Storage B7A	1942	185	Required	185.550	Missing electrical cover plate	Provide new cover plate	Improve	Provide new cover plate	ea.	1	strict Employee	Safety Standards	\$2		Fire Prevention
	Social Studies B4				Tell Owner	Wall base has come detached from wall	Replace wall base	Repair						*		
A12	Storage T21	Torry	185	Required	185.370.g.4	Smoke rating at pipes	Seal opening around pipe with fire caulk	Improve	Seal opening around pipe with fire caulk	ea.		District Employee	Safety Standards	\$150		Fire Prevention
A6	Storage T27	Torry	185	Required	185.390.g.2	No rating on door	Install new rated door/hardware	Improve	Install new rated door/hardware	ea.	1	Contractors	Safety Standards	\$1,350		Fire Prevention
A4	Storage T27	Torry	185	Required	185.390.g.2	No closer	Install new closer	Improve	Install new closer	ea.	1	Contractors	Safety Standards	\$310		Fire Prevention
A6	Storage T21	Torry	185	Required	185.390.g.2	No rating on door	Install new rated door/hardware	Improve	Install new rated door/hardware	ea.	1	Contractors	Safety Standards	\$1,350		Fire Prevention
A14	Stair S16	Torry	185	Urgent	185.370.m.2	Multiple egress doors inoperable at south elevation of gym (9 total)	Install new exterior doors/hardware (9 total)	Improve	Install new exterior doors/hardware (9 total)	ea.	9	Contractors	Safety Standards	\$45,425		Fire Prevention
A7	Storage B9B	1942	185	Required	185.390.g.4	Storage Room under stairs	Install (2) 5/8" FR Gyp board on hat channels at ceiling/below stairs	Improve	Install (2) 5/8" FR Gyp board on hat channels at ceiling/below stairs	s.f.	90	Contractors	Safety Standards	\$730		Fire Prevention
a6	Storage B9B	1942	185	Required	185.390.g.2	No rating on door	Install new rated door/hardware	Improve	Install new rated door/hardware	ea.	1	Contractors	Safety Standards	\$1,350		Fire Prevention
	FIRST FLOOR:															
	C.A.R.E Room				Tell Owner	Cords across floor, tripping hazard								*		
	Foreign Language 154				Tell Owner	Glass in windows/display case is not labeled as safety glass								*		
A8	Foreign Language 154	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	Foreign Language 152	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	Foreign Language 150	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	Foreign Language 148	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	Drivers Ed. 146	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	English 144	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	English 142	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	Math 140	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	English 138	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	English 136	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	English 134	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	English 132	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	English 130	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	Foods 131	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	FCS 133	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	English 135	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	Foreign Language 151	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	Foreign Language 149	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A8	Child Development 147	1955/61	185	Required	185.390.g.2	non-self closing hold-open not allowed	replace with self-closing hardware	Improve	replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
	3D Art Room - outside of C.R.				Tell Owner	Glass in display case is not labeled as safety glass	Replace with safety glazing							*		
	Photo 168				Tell Owner	Glass in display case is not labeled as safety glass	Replace with safety glazing							*		
	Special Ed-116				Tell Owner	Glass in display case is not labeled as safety glass	Replace with safety glazing							*		
	Special Ed-118				Tell Owner	Glass in display case is not labeled as safety glass	Replace with safety glazing							*		
	English/Drama/Speech				Tell Owner	Glass in display case is not labeled as safety glass (2)	Replace with safety glazing (2)							*		
	A.D. Work Room T104															
	Storage 163A	2011	2009 ICC	Recommended		non-self closing hold-open not allowed	Replace with self-closing hardware	Improve	Replace with self-closing hardware	ea.	1	Contractors	Safety Standards	\$335		Fire Prevention
A9	Stage 100A	1942	185	Urgent	185.360.e.1	Stage curtains are not labeled as flameproof or fire retardant	Replace curtain with 1-hour rated partition assembly and (2) 3'-0" fire-rated doors/hardware	Improve	Replace curtain with 1-hour rated partition assembly and (2) 3'-0" fire-rated doors/hardware	s.f.	710	Contractors	Safety Standards	\$10,500		Fire Prevention
A1	Stage 100A	1942	185	Urgent	185.370.b.4	Floor material missing and/or in disrepair causing trip hazard	Replace/repair missing planks	Repair	Replace/repair missing planks	s.f.	50	Contractors	Safety Standards	\$830		Fire Prevention
	Data Center 120B				Tell Owner	Missing ceiling tile(s)	Replace missing ceiling tile(s)							*		

Ref. Plan	Room Name	Location	Code	Priority Code	Rule Violated	Description of Violation	Recommendation to Correct	Action ID	Specifications	Units of Measure	Quantity	Labor Code	Work Type	Estimated Cost	Estimated Completion Date {MM/DD/YYYY}	Funding Type
SECOND FLOOR:																
M1	255 OFFICE	1961 South	185	Required	185.457	OUTSIDE VENTILATION AIR SOURCE NOT PROVIDED.	PROVIDE OUTDOOR AIR TO ROOM.	Improve		EA.	1	Contractors	Safety Standards	\$3,000		
M2	243 WORK ROOM	1955 South	185	Required	185.460	EXHAUST AIR SYSTEM NOT PROVIDED.	PROVIDE EXHAUST.	Improve		EA.	1	Contractors	Safety Standards	\$2,500		
M2	234 STORAGE/PREP	1955 South	185	Required	185.460	EXHAUST AIR SYSTEM NOT PROVIDED.	PROVIDE EXHAUST.	Improve		EA.	1	Contractors	Safety Standards	\$2,500		
M2	214 PHYSICS	1942	185	Required	185.460	EXHAUST AIR SYSTEM NOT PROVIDED.	PROVIDE EXHAUST.	Improve		EA.	1	Contractors	Safety Standards	\$2,500		
M7	228A PREP	1975	175	Required	175.564	EXHAUST AIR HOOD NOT PROVIDED FOR OVEN.	PROVIDE HOOD AND EXHAUST.	Improve		EA.	1	Contractors	Safety Standards	\$5,000		
M1	225 WORK ROOM	1942	185	Required	185.457	OUTSIDE VENTILATION AIR SOURCE NOT PROVIDED.	PROVIDE OUTDOOR AIR TO ROOM.	Improve		EA.	1	Contractors	Safety Standards	\$3,000		
M2	225B JANITOR	1942	185	Required	185.460	EXHAUST AIR SYSTEM NOT PROVIDED.	PROVIDE EXHAUST.	Improve		EA.	1	Contractors	Safety Standards	\$2,500		
M1	287 MEZZANINE	1975 Ashbrook	175	Required	175.574	OUTSIDE VENTILATION AIR SOURCE NOT PROVIDED.	PROVIDE OUTDOOR AIR TO ROOM.	Improve		EA.	1	Contractors	Safety Standards	\$3,000		
PENTHOUSE/ROOF:																
M11	184 SOUTH CORRIDOR ROOF	2011	IMC 2009	Recommended	IMC 1107	REFRIGERANT PIPE INSULATION IS DETERIORATED AND HAS NO PROTECTIVE JACKET.	PROVIDE NEW INSULATION AND JACKET.	Improve		EA.	1	Contractors	Safety Standards	\$1,000		
M11	183 NORTH CORRIDOR ROOF	2011	IMC 2009	Recommended	IMC 1107	REFRIGERANT PIPE INSULATION IS DETERIORATED AND HAS NO PROTECTIVE JACKET.	PROVIDE NEW INSULATION AND JACKET.	Improve		EA.	1	Contractors	Safety Standards	\$1,000		
M18	T101 A.D. OFFICE ROOF	1961 Torry	185	Required	185.445	EXTERIOR DRYER VENT STACK IS DETERIORATED.	PROVIDE NEW VENT STACKS.	Improve		EA.	2	Contractors	Safety Standards	\$5,000		
M11	T101 A.D. OFFICE ROOF	1961 Torry	IMC 2009	Recommended	IMC 1107	REFRIGERANT PIPE INSULATION IS DETERIORATED AND HAS NO PROTECTIVE JACKET.	PROVIDE NEW INSULATION AND JACKET.	Improve		EA.	1	Contractors	Safety Standards	\$1,000		
M11	T103 A.D. SECT. ROOF	1961 Torry	IMC 2009	Recommended	IMC 1107	REFRIGERANT PIPE INSULATION IS DETERIORATED AND HAS NO PROTECTIVE JACKET.	PROVIDE NEW INSULATION AND JACKET.	Improve		EA.	1	Contractors	Safety Standards	\$1,000		
M11	T105 WOMEN'S ROOF	1961 Torry	IMC 2009	Recommended	IMC 1107	REFRIGERANT PIPE INSULATION IS DETERIORATED AND HAS NO PROTECTIVE JACKET.	PROVIDE NEW INSULATION AND JACKET.	Improve		EA.	1	Contractors	Safety Standards	\$1,000		
M11	C212A CORRIDOR ROOF	1961 South	IMC 2009	Recommended	IMC 1107	REFRIGERANT PIPE INSULATION IS DETERIORATED AND HAS NO PROTECTIVE JACKET.	PROVIDE NEW INSULATION AND JACKET.	Improve		L.S.	1	Contractors	Safety Standards	\$5,000		
M17	C212A CORRIDOR ROOF	1961 South	IMC 2009	Recommended	IMC 305	REFRIGERANT PIPING NEEDS SUPPORTED.	PROVIDE ADDITIONAL SUPPORTS.	Improve		L.S.	1	Contractors	Safety Standards	\$2,500		
M11	C212 CORRIDOR ROOF	1961 South	IMC 2009	Recommended	IMC 1107	REFRIGERANT PIPE INSULATION IS DETERIORATED AND HAS NO PROTECTIVE JACKET.	PROVIDE NEW INSULATION AND JACKET.	Improve		L.S.	1	Contractors	Safety Standards	\$5,000		
M17	C212 CORRIDOR ROOF	1961 South	IMC 2009	Recommended	IMC 305	REFRIGERANT PIPING NEEDS SUPPORTED.	PROVIDE ADDITIONAL SUPPORTS.	Improve		L.S.	1	Contractors	Safety Standards	\$2,500		
M11	C211A CORRIDOR ROOF	1955 South	IMC 2009	Recommended	IMC 1107	REFRIGERANT PIPE INSULATION IS DETERIORATED AND HAS NO PROTECTIVE JACKET.	PROVIDE NEW INSULATION AND JACKET.	Improve		L.S.	1	Contractors	Safety Standards	\$5,000		
M17	C211A CORRIDOR ROOF	1955 South	IMC 2009	Recommended	IMC 305	REFRIGERANT PIPING NEEDS SUPPORTED.	PROVIDE ADDITIONAL SUPPORTS.	Improve		L.S.	1	Contractors	Safety Standards	\$2,500		
M11	215 SPECIAL ED. ROOF	1942	IMC 2009	Recommended	IMC 1107	REFRIGERANT PIPE INSULATION IS DETERIORATED AND HAS NO PROTECTIVE JACKET.	PROVIDE NEW INSULATION AND JACKET.	Improve		L.S.	1	Contractors	Safety Standards	\$5,000		
M14	215 SPECIAL ED. ROOF	1942	IMC 2009	Recommended	IMC 305	REFRIGERANT PIPING NEEDS PIPE CURB.	PROVIDE CURB.	Improve		EA.	1	Contractors	Safety Standards	\$1,500		
M15	300 MECH. PENTHOUSE	1975	175	Recommended	175.510	PIPE INSULATION DETERIORATED AND/OR MISSING. CHILLED WATER PIPING HAS SURFACE CORROSION	REPLACE PIPING AND INSULATION.	Improve		L.S.	1	Contractors	Safety Standards	\$15,000		
M18	101 GREEN ROOM ROOF	1955	185	Required	185.445	EXTERIOR BOILER STACK IS DETERIORATED.	REPLACE STACK.	Improve		EA.	1	Contractors	Safety Standards	\$20,000		
PANTHERPLEX:																
M2	102 JANITOR	2010	IMC 2009	Required	IMC 502	EXHAUST AIR SYSTEM NOT PROVIDED FOR ROOM	PROVIDE EXHAUST.	Improve		EA.	1	Contractors	Safety Standards	\$2,500		
M2	106 TRAINER	2010	IMC 2009	Recommended	IMC 502	EXHAUST AIR SYSTEM NOT PROVIDED FOR ROOM	PROVIDE EXHAUST.	Improve		EA.	1	Contractors	Safety Standards	\$2,500		
M2	110 JANITOR	2010	IMC 2009	Required	IMC 502	EXHAUST AIR SYSTEM NOT PROVIDED FOR ROOM	PROVIDE EXHAUST.	Improve		EA.	1	Contractors	Safety Standards	\$2,500		
M2	208 JANITOR	2010	IMC 2009	Required	IMC 502	EXHAUST AIR SYSTEM NOT PROVIDED FOR ROOM	PROVIDE EXHAUST.	Improve		EA.	1	Contractors	Safety Standards	\$2,500		

Farnsworth Group

ISBE Health Life Safety Survey Information

#REF! Electrical

Ref. Plan Keynote	Room Name	Priority Code	Rule Violated	Description of Violation	Recommendation to Correct	Action ID	Specifications	Units of Measure	Quantity	Labor Code	Work Type	Estimated Cost	Estimated Completion Date {MM/DD/YYYY}	Funding Type
GENERAL:														
E27	GENERAL:	Required	IBC 2009 907.6.5	FIRE ALARM SYSTEM REQUIRED TO BE TESTED	TEST AND CERTIFY FIRE ALARM SYSTEM OPERATION	Improve		Ea.	1	Contractors	Safety Standards	\$5,000		
E28	GENERAL:	Required	IBC 2009 1006	EMERGENCY LIGHTING UNITS REQUIRED TO BE TESTED	TEST EMERGENCY LIGHTING UNITS. REPLACE ANY NON-FUNCTIONING EMERGENCY LIGHTING UNITS	Improve		Ea.	1	Contractors	Safety Standards	\$15,000		
E33	GENERAL:	Required	185.510	UNSEALED PENETRATIONS IN FIRE WALLS	SEAL PENETRATIONS IN FIRE WALLS	Improve		Ea.	1	Contractors	Safety Standards	\$5,000		
E35	GENERAL:	Required	185.510	ELECTRICAL WIRING AND PANELS ARE ORIGINAL 1942 VINTAGE AND BEYOND THEIR USEFUL LIFE.	REPLACE ELECTRICAL WIRING AND PANELS IN 1942 BUILDING	Repair		Sq. Ft.	23750	Contractors	Safety Standards	\$166,250		
E35	GENERAL:	Required	185.510	ELECTRICAL WIRING AND PANELS ARE ORIGINAL 1955 VINTAGE AND BEYOND THEIR USEFUL LIFE.	REPLACE ELECTRICAL WIRING AND PANELS IN 1955 BUILDING	Repair		Sq. Ft.	35536	Contractors	Safety Standards	\$248,752		
E35	GENERAL:	Required	185.510	ELECTRICAL WIRING AND PANELS ARE ORIGINAL 1961 VINTAGE AND BEYOND THEIR USEFUL LIFE.	REPLACE ELECTRICAL WIRING AND PANELS IN 1961 SOUTH BUILDING	Repair		Sq. Ft.	19048	Contractors	Safety Standards	\$133,336		
E35	GENERAL:	Required	185.510	ELECTRICAL WIRING AND PANELS ARE ORIGINAL 1961 VINTAGE AND BEYOND THEIR USEFUL LIFE.	REPLACE ELECTRICAL WIRING AND PANELS IN 1961 TORRY GYM BUILDING	Repair		Sq. Ft.	27974	Contractors	Safety Standards	\$195,818		
	GENERAL:	Required	185.510	EXISTING ELECTRICAL PANELS DO NOT HAVE ACCURATE OR COMPLETE CIRCUIT DIRECTORIES OR PANEL SOURCE LABELS.	TRACE EXISTING ELECTRICAL CIRCUITS. PROVIDE ACCURATE CIRCUIT DIRECTORIES AND PANEL SOURCE LABELS.	Improve		Sq. Ft.	106308	Contractors	Safety Standards	\$26,577		
	GENERAL:	Required	2009 IBC	INTERCOM SYSTEM USED FOR EMERGENCY COMMUNICATION IS FAILING AND REPLACEMENT PARTS ARE BOCOMING UNAVAILABLE.	REPLACE INTERCOM SYSTEM.	Repair		Ea.	1	Contractors	Safety Standards	\$25,000		
	GENERAL:	Recommended	2018 IECC	MAJORITY OF LIGHTING IS CURRENTLY FLUORESCENT	UPGRADE LIGHTING TO LED	Improve		Sq. Ft.	221150	Contractors	Energy Conservation	\$552,875		
	GENERAL:	Recommended	2018 IECC	MINIMAL EXISTING MOTION DETECTION CONTROLLED LIGHTING	ADD MOTION DETECTORS TO LIGHTING	Improve		Sq. Ft.	150000	Contractors	Energy Conservation	\$225,000		
BASEMENT:														
E4	STAIR 09	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E16	SOCIAL STUDIES B3	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E16	SOCIAL STUDIES B2	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E5	CORRIDOR C001B	Urgent	BOCA 1993 1024	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C001B	Urgent	BOCA 1993 1023	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C002B	Urgent	BOCA 1993 1023	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C002A	Urgent	BOCA 1993 1023	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E4	CORRIDOR C002A	Urgent	BOCA 1993 1024	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		

E14	CORRIDOR C003	Urgent	BOCA 1993 1023	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E39	MECHANICAL B27	Required	185.510	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Rebuild		Ea.	1	Contractors	Safety Standards	\$50		
E40	MECHANICAL B27	Required	185.510	ELECTRICAL EQUIPMENT DAMAGED	REPAIR ELECTRICAL EQUIPMENT	Repair		Ea.	1	Contractors	Safety Standards	\$500		
E9	TOILET B27	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E9	TOILET B28	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E10	CORRIDOR @ B27	Required	IBC 2009 907.5.2.1	FIRE ALARM STROBE HORN OMITTED	PROVIDE FIRE ALARM HORN/STROBE LIGHT	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	CORRIDOR C004	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E8	CORRIDOR C004	Required	IBC 2009 907.2.3	MANUAL FIRE ALARM PULL STATION OMITTED	PROVIDE MANUAL FIRE ALARM PULL STATION	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	CORRIDOR C004	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	STAIR 7	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E11	CORRIDOR C004	Urgent	IBC 2009 1011	DIRECTIONAL ARROW OMITTED FROM EXIT SIGN	DIRECTIONAL ARROW ON EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$50		
E4	CORRIDOR C005	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E1	CORRIDOR C005	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	CORRIDOR C008A	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C008A	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E8	CORRIDOR C008A	Required	IBC 2009 907.2.3	MANUAL FIRE ALARM PULL STATION OMITTED	PROVIDE MANUAL FIRE ALARM PULL STATION	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C008A	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E4	STAIR 6 S6	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E1	IT B14	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	COMPUTER LAB B13	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	COMPUTER LAB B12	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	COMPUTER LAB B16	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	COMPUTER LAB B15	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	COMPUTER LAB B10	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	CORRIDOR C008B	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C008B	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E4	CORRIDOR C008C	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E1	IT B17	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	STUDY HALL B20	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E4	STUDY HALL B20	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	3	Contractors	Safety Standards	\$900		
E10	STUDY HALL B20	Required	IBC 2009 907.5.2.1	FIRE ALARM STROBE HORN OMITTED	PROVIDE FIRE ALARM HORN/STROBE LIGHT	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E39	STUDY HALL B20	Required	175.610	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Improve		Ea.	1	Contractors	Safety Standards	\$50		
E39	MECHANICAL B21A	Required	175.610	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Improve		Ea.	1	Contractors	Safety Standards	\$50		
	MECHANICAL B21A	Urgent	IBC 2009 903.4.2	SPRINKLER TAMPER AND FLOW SWITCHES NOT CONNECTED TO FIRE ALARM SYSTEM	CONNECT SPRINKLER TAMPER AND FLOW SWITCHES TO FIRE ALARM SYSTEM	Improve		Ea.	1	Contractors	Safety Standards	\$1,000		
E42	MECHANICAL B21A	Urgent	IBC 2009 907.2.3	COVER ON SMOKE DETECTOR	REMOVE COVER FROM SMOKE DETECTOR	Repair		Ea.	1	Contractors	Safety Standards	\$50		
E42	MECHANICAL B21C	Urgent	IBC 2009 907.2.3	COVER ON HEAT DETECTOR	REMOVE COVER FROM HEAT DETECTOR	Repair		Ea.	1	Contractors	Safety Standards	\$50		
E40	MECHANICAL B21C	Required	175.610	ABANDONED WIRING	REMOVE ABANDONED WIRING	Remove		Ea.	1	Contractors	Safety Standards	\$150		
E42	MECHANICAL B21B	Urgent	IBC 2009 907.2.3	COVER ON HEAT DETECTOR	REMOVE COVER FROM HEAT DETECTOR	Repair		Ea.	1	Contractors	Safety Standards	\$50		
E34	MECHANICAL B21B	Urgent	IBC 2009 907.3.1	DUCT SMOKE DETECTOR OMITTED	PROVIDE DUCT SMOKE DETECTOR	Improve		Ea.	2	Contractors	Safety Standards	\$1,500		
E17	MECHANICAL B21B	Required	175.610	STARTER/DISCONNECT WORKING SPACE VIOLATION	RELOCATE STARTER/DISCONNECT TO CORRECT WORKING SPACE VIOLATION	Relocate		Ea.	2	Contractors	Safety Standards	\$1,000		
	TOILET B21E	Required	175.610	NON-GFI RECEPTACLE AT SINK	REMOVE LIGHTING FIXTURE WITH GFI RECEPTACLE	Remove		Ea.	1	Contractors	Safety Standards	\$200		
E1	CORRIDOR C006B	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C006B	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		

E1	CORRIDOR C006A	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C006A	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E1	BUSINESS CLASSROOM B9	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E39	BUSINESS CLASSROOM B9	Required	175.610	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Improve		Ea.	1	Contractors	Safety Standards	\$50		
E37	LOUNGE B11	Urgent	175.610	NON-GFI RECEPTACLE AT SINK	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLE	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E4	CORRIDOR C007	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E5	CORRIDOR C0007	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	STORAGE B9A	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E5	STAIR 1 S1	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	STORAGE B9B	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E40	STAIR 1 S1	Required	175.610	ABANDONED WIRING	REMOVE ABANDONED WIRING	Remove		Ea.	1	Contractors	Safety Standards	\$150		
E4	STAIR 10 S10	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E9	STAIR 10 S10	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E4	LOCKER ROOM B18	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E4	STAIR 19	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E4	STAIR 2 S2	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E9	STAIR 2 S2	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E42	OLD BOILER ROOM B22	Urgent	IBC 2009 907.2.3	COVER ON HEAT DETECTOR	REMOVE COVER FROM HEAT DETECTOR	Repair		Ea.	1	Contractors	Safety Standards	\$50		
E39	OLD BOILER ROOM B22	Required	185.510	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Improve		Ea.	1	Contractors	Safety Standards	\$50		
E32	OLD BOILER ROOM B22	Required	185.510	DROP CORD UTILIZED FOR PERMANENT WIRING	REPLACE DROP CORD WITH PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E37	OLD BOILER ROOM B22	Urgent	185.510	NON-GFI RECEPTACLE AT SINK	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLE	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E39	OLD BOILER ROOM B22	Required	185.510	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Improve		Ea.	1	Contractors	Safety Standards	\$50		
E39	MECHANICAL EQUIP B23	Required	185.510	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Improve		Ea.	2	Contractors	Safety Standards	\$500		
E37	MECHANICAL EQUIP B23	Urgent	185.510	NON-GFI RECEPTACLE AT SINK	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLE	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E17	MECHANICAL EQUIP B23	Required	185.510	STARTER/DISCONNECT WORKING SPACE VIOLATION	RELOCATE STARTER/DISCONNECT TO CORRECT WORKING SPACE VIOLATION	Relocate		Ea.	2	Contractors	Safety Standards	\$1,500		
E14	CORRIDOR C010	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C010	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E9	CORRIDOR C010	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E14	CORRIDOR C009	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C009	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E9	CORRIDOR C009	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E5	CORRIDOR C009	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	STORAGE B19B	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	STAIR 20 S20	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E37	LOCKER ROOM B20	Urgent	185.510	NON-GFI RECEPTACLE AT SINK	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLE	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E4	LOCKER ROOM B20	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E4	STAIR S11	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E8	STAIR S11	Required	IBC 2009 907.2.3	MANUAL FIRE ALARM PULL STATION OMITTED	PROVIDE MANUAL FIRE ALARM PULL STATION	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E39	BOILER ROOM B24	Required	185.510	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Improve		Ea.	2	Contractors	Safety Standards	\$500		
E37	BOILER ROOM B24	Urgent	185.510	NON-GFI RECEPTACLE AT SINK	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLE	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E9	CORRIDOR C011	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	2	Contractors	Handicapped Access	\$1,000		
E5	CORRIDOR C011	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR T000D	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E4	LOCKER ROOM T29	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	3	Contractors	Safety Standards	\$900		
E14	LOCKER ROOM T29	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E5	LOCKER ROOM T29	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	3	Contractors	Safety Standards	\$1,500		

E16	ENGLISH 142	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E16	ENGLISH 140	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	STAIR 8	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E4	CORRIDOR C108A	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E5	CORRIDOR C108A	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C108A	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E10	CORRIDOR C108A	Required	IBC 2009 907.5.2.1	FIRE ALARM STROBE HORN OMITTED	PROVIDE FIRE ALARM HORN/STROBE LIGHT	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C108	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E5	CORRIDOR C108	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C108	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C107	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E5	CORRIDOR C107	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C107	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E16	ENGLISH 135	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E16	FCS 133	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E16	ENGLISH 132	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E16	ENGLISH 130	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E37	FOODS 131	Urgent	185.510	CONFIRM RECEPTACLES ARE GFI	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLES	Improve		Ea.	1	Contractors	Safety Standards	\$1,000		
E9	WORKROOM 143	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E9	RR 143A	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E24	WORKROOM 143	Required	185.510	DROP CORD UTILIZED FOR PERMANENT WIRING	REPLACE DROP CORD WITH PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E38	CHILD DEVELOPMENT	Urgent	NEC 406.12	NON-TAMPER PROOF RECEPTACLES	REPLACE RECEPTACLES WITH TAMPER PROOF TYPE	Improve		Ea.	15	Contractors	Safety Standards	\$2,000		
E16	FOREIGN LANG. 149	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E16	FOREIGN LANG. 151	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C106	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	CORRIDOR C106	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E9	ELEVATOR EL2 LOBBY	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E1	ELEVATOR EL2	Urgent	ANSI A17.1	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	2	Contractors	Safety Standards	\$1,500		
E21	ELEVATOR EL2	Urgent	ANSI A17.1	CONFIRM ELEVATOR RECALL FUNCTIONING	CONFIRM ELEVATOR RECALL FUNCTIONING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	SOUTH CORRIDOR 184	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	SOUTH CORRIDOR 184	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E4	SOUTH CORRIDOR 184	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	3	Contractors	Safety Standards	\$900		
E10	SOUTH CORRIDOR 184	Required	IBC 2009 907.5.2.1	FIRE ALARM STROBE HORN OMITTED	PROVIDE FIRE ALARM HORN/STROBE LIGHT	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E41	SOUTH CORRIDOR 184	Urgent	IBC 2009 1006	EMERGENCY LIGHTING BROKEN	REPAIR OR REPLACE BROKEN EMERGENCY LIGHT	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	SOUTH CORRIDOR 184	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	NORTH CORRIDOR 183	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	3	Contractors	Safety Standards	\$1,500		
E9	NORTH CORRIDOR 183	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E4	NORTH CORRIDOR 183	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	3	Contractors	Safety Standards	\$900		
E10	NORTH CORRIDOR 183	Required	IBC 2009 907.5.2.1	FIRE ALARM STROBE HORN OMITTED	PROVIDE FIRE ALARM HORN/STROBE LIGHT	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	NORTH CORRIDOR 183	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		

E37	BOYS 113	Urgent	185.510	NON-GFI RECEPTACLE IN BATHROOM	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLE	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E4	CORRIDOR C104	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E5	CORRIDOR C104	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E14	CORRIDOR C105	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	STAIR 7	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E10	STAIR 7	Required	IBC 2009 907.5.2.1	FIRE ALARM STROBE HORN OMITTED	PROVIDE FIRE ALARM HORN/STROBE LIGHT	Improve		Ea.	1	Contractors	Safety Standards	\$500		
	STORAGE 116B	Urgent	NEC	RECPTACLE IN TIME OUT ROOM	REMOVE RECEPTACLE FROM TIME OUT ROOM	Remove		Ea.	1	Contractors	Safety Standards	\$250		
E9	STAIR 1	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E5	CORRIDOR C102	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	CORRIDOR C102	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C102	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	CONFERENCE 120A	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E9	CONFERENCE 120C	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E9	WORKROOM 120D	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	2	Contractors	Handicapped Access	\$1,000		
E1	JANITOR CLOSET 120F	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	CLOSET 120G	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	LIBRARY 120	Urgent	175.480	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	4	Contractors	Safety Standards	\$1,200		
E5	LIBRARY 120	Urgent	175.480	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E40	LIBRARY 120	Required	175.610	FLOOR OUTLET BROKEN	REPAIR BROKEN FLOOR OUTLET	Repair		Ea.	1	Contractors	Safety Standards	\$250		
E4	PEER TUTOR 120UN	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E5	PEER TUTOR 120UN	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	PEER TUTOR 120US	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E5	PEER TUTOR 120US	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E5	ELEVATOR 3	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	ELEVATOR 3	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	ENTRY #1	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C103	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	CORRIDOR C103	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	TOILET 112A	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E14	CORRIDOR C100	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C100	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E41	CORRIDOR C100	Urgent	185.370	EMERGENCY LIGHTING BROKEN	REPAIR OR REPLACE BROKEN EMERGENCY LIGHT	Improve		Ea.	1	Contractors	Safety Standards	\$500		
	OFFICE 110D	Urgent	IBC 2009 907.2.3	TAPE COVERING SMOKE DETECTOR	REMOVE TAPE FROM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$100		
E4	WEST GYM 100	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	4	Contractors	Safety Standards	\$1,200		
E5	WEST GYM 100	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	6	Contractors	Safety Standards	\$3,000		
E20	WEST GYM 100	Required	NEC	ELECTRICAL DEVICES SUBJECT TO PHYSICAL DAMAGE	PROVIDE WIRE GUARDS ON FIRE ALARM DEVICES, EXIT SIGNS AND EMERGENCY LIGHTING UNITS	Improve		Ea.	12	Contractors	Safety Standards	\$1,500		
E14	WEST GYM 100	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E8	WEST GYM 100	Required	IBC 2009 907.2.3	MANUAL FIRE ALARM PULL STATION OMITTED	PROVIDE MANUAL FIRE ALARM PULL STATION	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	STAGE 100A	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	2	Contractors	Handicapped Access	\$1,000		
E40	STAGE 100A	Required	NEC	DIMMING RACK FULL OF DUST AND DEBRIS	CLEAN DIMMER RACK	Repair		Ea.	1	Contractors	Safety Standards	\$200		
E32	STAGE 100A	Required	185.510	DROP CORD UTILIZED FOR PERMANENT WIRING	REPLACE DROP CORDS WITH PERMANENT WIRING	Improve		Ea.	6	Contractors	Safety Standards	\$4,000		
E1	STAGE 100A	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	3	Contractors	Safety Standards	\$1,500		
E40	STAGE 100A	Required	185.510	DAMAGED AND DETERIORATED WIRING UNDER STAGE	REPAIR DAMAGED AND DETERIORATED WIRING UNDER STAGE	Repair		Ea.	1	Contractors	Safety Standards	\$4,000		
E5	STAGE 100A	Urgent	185.370	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E37	GREEN ROOM 101	Urgent	185.510	NON-GFI RECEPTACLE AT SINK	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLE	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E37	TOILET C111B	Urgent	185.510	NON-GFI RECEPTACLE AT SINK	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLE	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E4	CORRIDOR C111	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		

E1	CORRIDOR C111	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E5	CORRIDOR C111	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C111	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	STORAGE BY CORRIDOR C111	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	MULTIPURPOSE SPACE 180	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	3	Contractors	Safety Standards	\$1,500		
E16	MULTIPURPOSE SPACE 180	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E40	MULTIPURPOSE SPACE 180	Required	IBC 2009 CHAPTER 27	EXIT SIGN NOT FUNCTIONING	REPLACE OR REPAIR NON-FUNCTIONING EXIT SIGN	Repair		Ea.	1	Contractors	Safety Standards	\$300		
E4	MULTIPURPOSE SPACE 180	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	6	Contractors	Safety Standards	\$1,800		
E41	MULTIPURPOSE SPACE 180	Urgent	IBC 2009 1006	EMERGENCY LIGHTING BROKEN	REPAIR OR REPLACE BROKEN EMERGENCY LIGHT	Improve		Ea.	8	Contractors	Safety Standards	\$3,200		
E8	MULTIPURPOSE SPACE 180	Required	IBC 2009 907.2.3	MANUAL FIRE ALARM PULL STATION OMITTED	PROVIDE MANUAL FIRE ALARM PULL STATION	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	DARK ROOM 169	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E4	RECEPTION 161	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E4	MAIN ENTRY CORRIDOR C112	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	3	Contractors	Safety Standards	\$900		
E41	MAIN ENTRY CORRIDOR C112	Urgent	IBC 2009 1006	EMERGENCY LIGHTING BROKEN	REPAIR OR REPLACE BROKEN EMERGENCY LIGHT	Improve		Ea.	4	Contractors	Safety Standards	\$1,600		
	MAIN ENTRY CORRIDOR C112	Urgent	IBC 2009 1006	EXIT SIGN NOT VISIBLE	REVISE EXIT SIGN LOCATION	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	ENTRY VESTIBULE 160	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E41	ENTRY VESTIBULE 160	Urgent	IBC 2009 1006	EMERGENCY LIGHTING BROKEN	REPAIR OR REPLACE BROKEN EMERGENCY LIGHT	Improve		Ea.	2	Contractors	Safety Standards	\$800		
E8	ENTRY VESTIBULE 160	Required	IBC 2009 907.2.3	MANUAL FIRE ALARM PULL STATION OMITTED	PROVIDE MANUAL FIRE ALARM PULL STATION	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	ENTRY VESTIBULE 160	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E1	WORK ROOM 163	Urgent	IBC 2009 907.2.3	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	GUIDANCE 167	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E1	CORRIDOR C118	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E18	CORRIDOR C118	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OBSTRUCTED	MOOVE COOLER	Relocate		Ea.	1	Contractors	Safety Standards	\$0		
E4	CORRIDOR C118	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E8	CORRIDOR C118	Required	IBC 2009 907.2.3	MANUAL FIRE ALARM PULL STATION OMITTED	PROVIDE MANUAL FIRE ALARM PULL STATION	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E21	ELEVATOR EL1A	Urgent	ANSI A17.1	CONFIRM ELEVATOR RECALL FUNCTIONING	CONFIRM ELEVATOR RECALL FUNCTIONING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	COORIDOR C117	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E11	COORIDOR C117	Urgent	IBC 2009 1011	DIRECTIONAL ARROW OMITTED FROM EXIT SIGN	DIRECTIONAL ARROW ON EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$50		
E9	COORIDOR C116	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E5	COORIDOR T000A	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR T000A	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E40	UPPER BALCONY EAST T100E	Required	185.510	ELECTRICAL DEVICE LOOSE	SECURE ELECTRICAL DEVICE	Repair		Ea.	1	Contractors	Safety Standards	\$250		
E4	UPPER BALCONY EAST T100E	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E41	UPPER BALCONY EAST T100E	Urgent	IBC 2009 1006	EMERGENCY LIGHTING BROKEN	REPAIR OR REPLACE BROKEN EMERGENCY LIGHT	Improve		Ea.	3	Contractors	Safety Standards	\$1,500		
E4	UPPER BALCONY WEST T100W	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E41	UPPER BALCONY WEST T100W	Urgent	IBC 2009 1006	EMERGENCY LIGHTING BROKEN	REPAIR OR REPLACE BROKEN EMERGENCY LIGHT	Improve		Ea.	3	Contractors	Safety Standards	\$1,500		
E4	GYM T000	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	4	Contractors	Safety Standards	\$600		
E41	GYM T000	Urgent	IBC 2009 1006	EMERGENCY LIGHTING BROKEN	REPAIR OR REPLACE BROKEN EMERGENCY LIGHT	Improve		Ea.	6	Contractors	Safety Standards	\$3,000		
	GYM T000	Urgent	185.510	BLEACHER WIRING DETERIORATED	Replace bleacher wiring	Repair		Ea.	1	Contractors	Safety Standards	\$50,000		
E40	UPPER BALCONY WEST T100W	Required	185.510	CORD DETERIORATED ON WINCH	REPLACE CORD ON WINCH	Repair		Ea.	1	Contractors	Safety Standards	\$500		
E39	UPPER BALCONY WEST T100W	Required	185.510	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Improve		Ea.	1	Contractors	Safety Standards	\$50		
E9	COORIDOR C113	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E1	CORRIDOR C113	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		

E14	CORRIDOR C213	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E5	CORRIDOR C209	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E5	CORRIDOR C210	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C210	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E14	CORRIDOR C210	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E5	CORRIDOR C211	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C211	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E14	CORRIDOR C211	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E5	CORRIDOR C211A	Urgent	IBC 2009 1006	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C211A	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E14	CORRIDOR C211A	Urgent	IBC 2009 1011	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	STAIR 8	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E4	STAIR 9	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E9	TOILET 243A	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E9	WORK ROOM 243	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E16	SPECIAL ED 249	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	SPECIAL ED 249	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E37	MATH 247	Urgent	175.610	NON-GFI RECEPTACLE AT SINK	REPLACE NON-GFI RECEPTACLE WITH GFI RECEPTACLE	Improve		Ea.	1	Contractors	Safety Standards	\$250		
E40	S.E. OFFICE 257	Required	IBC 2009 CHAPTER 27	RECEPTACLE BROKEN	REPLACE RECEPTACLE	Repair		Ea.	1	Contractors	Safety Standards	\$250		
E40	S.E. OFFICE 257	Required	IBC 2009 907.2.3	SMOKE DETECTOR INSTALLED ABOVE CEILING	REVISE SMOKE DETECTOR INSTALLATION TO CEILING	Repair		Ea.	1	Contractors	Safety Standards	\$250		
E24	CHEMISTRY 236	Required	IBC 2009 CHAPTER 27	DROP CORD UTILIZED FOR PERMANENT WIRING	REPLACE DROP CORD WITH PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E43	CHEMISTRY 236	Required	IBC 2009	GAS SHUT OFF SWITCH NOT LABELED	LABEL GAS SHUT OFF SWITCH	Improve		Ea.	2	Contractors	Safety Standards	\$100		
E43	CHEMISTRY 231	Required	IBC 2009	GAS SHUT OFF SWITCH NOT LABELED	LABEL GAS SHUT OFF SWITCH	Improve		Ea.	2	Contractors	Safety Standards	\$100		
E39	CHEMISTRY 231	Required	IBC 2009 CHAPTER 27	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Rebuild		Ea.	1	Contractors	Safety Standards	\$50		
E14	CORRIDOR C208	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E5	CORRIDOR C207	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E5	CORRIDOR C206	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E16	PHYSICS 217	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E16	SPECIAL ED 215	Required	NEC 400.8	DROP CORD ROUTED THROUGH LAY-IN CEILING	REPLACE DROP CORD WITH RECEPTACLE AND PERMANENT WIRING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C203	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C203	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E4	CORRIDOR C202	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E5	CORRIDOR C202	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	CORRIDOR C202	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E14	STUDY HALL 210	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E4	STUDY HALL 210	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$600		
E5	STUDY HALL 210	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C201	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E5	CORRIDOR C201	Urgent	185.370.a.6.C	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	CORRIDOR C201	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E14	CORRIDOR C201	Urgent	185.370	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	WORK ROOM 225	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E34	MECHANICAL MEZZ.	Urgent	IBC 2009 907.3.1	DUCT SMOKE DETECTOR OMITTED	PROVIDE DUCT SMOKE DETECTOR	Improve		Ea.	3	Contractors	Safety Standards	\$2,250		
E39	MECHANICAL MEZZ.	Required	185.510	COVER OMITTED ON J-BOX	PROVIDE COVER FOR J-BOX	Rebuild		Ea.	1	Contractors	Safety Standards	\$50		
E4	CORRIDOR C204	Urgent	185.370.a.6.C	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E43	PHYSICS 214	Required	IBC 2009	GAS SHUT OFF SWITCH NOT LABELED	LABEL GAS SHUT OFF SWITCH	Improve		Ea.	1	Contractors	Safety Standards	\$50		
E1	CORRIDOR C222	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	CORRIDOR C222	Urgent	175.480	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E5	CORRIDOR C222	Urgent	175.480	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E14	CORRIDOR C222	Urgent	175.480	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E9	CORRIDOR C222	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E4	CORRIDOR C205	Urgent	175.480	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		

E5	CORRIDOR C205	Urgent	175.480	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C205	Urgent	175.480	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E9	CORRIDOR C205	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E42	STORAGE 224A	Urgent	IBC 2009 907.2.3	COVER ON SMOKE DETECTOR	REMOVE COVER FROM SMOKE DETECTOR	Repair		Ea.	1	Contractors	Safety Standards	\$50		
E4	STAIR 3	Urgent	175.480	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E43	BIOLOGY 226	Required	IBC 2009	GAS SHUT OFF SWITCH NOT LABELED	LABEL GAS SHUT OFF SWITCH	Improve		Ea.	2	Contractors	Safety Standards	\$100		
E43	ANATOMY 227	Required	IBC 2009	GAS SHUT OFF SWITCH NOT LABELED	LABEL GAS SHUT OFF SWITCH	Improve		Ea.	2	Contractors	Safety Standards	\$100		
E43	BIOLOGY 228	Required	IBC 2009	GAS SHUT OFF SWITCH NOT LABELED	LABEL GAS SHUT OFF SWITCH	Improve		Ea.	2	Contractors	Safety Standards	\$100		
E43	BIOLOGY 229	Required	IBC 2009	GAS SHUT OFF SWITCH NOT LABELED	LABEL GAS SHUT OFF SWITCH	Improve		Ea.	2	Contractors	Safety Standards	\$100		
E43	PREP 228A	Required	IBC 2009	GAS SHUT OFF SWITCH NOT LABELED	LABEL GAS SHUT OFF SWITCH	Improve		Ea.	3	Contractors	Safety Standards	\$150		
E4	CORRIDOR C194	Urgent	175.480	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E5	CORRIDOR C194	Urgent	175.480	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E14	CORRIDOR C194	Urgent	175.480	EXIT SIGN OMITTED	PROVIDE EXIT SIGN	Improve		Ea.	2	Contractors	Safety Standards	\$1,000		
E1	CORRIDOR C194	Urgent	IBC 2009 715.4.8	FIRE ALARM SMOKE DETECTOR OMITTED	PROVIDE FIRE ALARM SMOKE DETECTOR	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E4	STAIR S6	Urgent	175.480	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E5	STAIR S6	Urgent	175.480	EMERGENCY LIGHTING OMITTED	PROVIDE EMERGENCY LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$500		
E40	MECHANICAL 285	Required	175.610	ELECTRICAL EQUIPMENT DAMAGED	REPAIR ELECTRICAL EQUIPMENT	Repair		Ea.	1	Contractors	Safety Standards	\$500		
E43	MECHANICAL 285	Required	IBC 2009	GAS SHUT OFF SWITCH NOT LABELED	LABEL GAS SHUT OFF SWITCH	Improve		Ea.	1	Contractors	Safety Standards	\$50		
E17	MECHANICAL 285	Required	175.610	STARTER/DISCONNECT WORKING SPACE VIOLATION	RELOCATE STARTER/DISCONNECT TO CORRECT WORKING SPACE VIOLATION	Relocate		Ea.	1	Contractors	Safety Standards	\$500		
E39	ROOF	Required	185.510	COVER OMITTED ON J-BOX AND RACEWAY BROKEN	PROVIDE COVER FOR J-BOX AND REPAIR RACEWAY	Rebuild		Ea.	1	Contractors	Safety Standards	\$500		
PANTHERPLEX														
E39	BUILDING EXTERIOR	Required	IBC 2009 CHAPTER 27	COVER OMITTED ON RECEPTACLE	PROVIDE COVER FOR RECEPTACLE	Repair		Ea.	1	Contractors	Safety Standards	\$50		
E4	VIEWING ROOM 201	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E9	VIEWING ROOM 201	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		
E4	CORRIDOR 205	Urgent	IBC 2009 1006	UN-SWITCHED NIGHT LIGHTING OMITTED	PROVIDE UN-SWITCHED NIGHT LIGHTING	Improve		Ea.	1	Contractors	Safety Standards	\$300		
E9	CORRIDOR 205	Required	IBC 2009 907.5.2.3	FIRE ALARM STROBE LIGHT OMITTED	PROVIDE FIRE ALARM STROBE LIGHT	Improve		Ea.	1	Contractors	Handicapped Access	\$500		

Ref. Plan
Keynote

Room Name	Priority Code	Rule Violated	Description of Violation	Recommendation to Correct	Action ID	Specifications	Units of Measure	Quantity	Labor Code	Work Type	Estimated Cost	Estimated Completion Date {MM/DD/YYYY}	Funding Type	
GENERAL:														
BASEMENT:														
P3		TOILET B28	Required	185.710, IPC 890.630.e)	NO HOT WATER AT LAVATORY	CONNECT HOT WATER TO FIXTURE	Improve		EA.	1	Contractors	Safety Standards	\$500	
P5		TOILET B27	Required	185.710, IPC 890.1230	MISSING RELIEF VALVE DISCHARGE PIPE ON WATER HEATER	PIPE RELIEF VALVE TO 6" ABOVE FLOOR	Improve		EA.	1	Contractors	Safety Standards	\$300	
P26		TOILET B27	Required	185.710, IPC 890.680.e)	MISSING FLOOR DRAIN AT WATER HEATER	INSTALL FLOOR DRAIN	Improve		EA.	1	Contractors	Safety Standards	\$1,000	
P25		TOILET B19A	Required	185.710, IPC 890.200	WATER CLOSET NOT FUNCTIONAL	REPLACE WATER CLOSET	Improve		EA.	1	Contractors	Safety Standards	\$750	
P7		BOILER ROOM B24	Required	185.710, IPC 890.200	WATER HEATER GAS PRV MISSING VENT CONNECTION	RECONNECT VENTS	Improve		EA.	2	Contractors	Safety Standards	\$500	
P15		TRAINING ROOM T43	Required	185.710, IPC 890.1010	ICE MAKER DRAIN IMPROPERLY INSTALLED	INSTALL TRAPPED AND VENTED INDIRECT WASTE CONNECTION	Improve		EA.	1	Contractors	Safety Standards	\$750	
P12		TRAINING ROOM T43	Required	185.710, IPC 890.1130.f)3)	MISSING BACKFLOW PREVENTER AT ICE MAKER	INSTALL BACKFLOW PREVENTER IN WATER CONNECTION TO ICE MAKER	Improve		EA.	1	Contractors	Safety Standards	\$500	
P17		TRAINING ROOM T43	Required	185.710, IPC 890.120	MISSING LAVATORY IN RESTROOM	INSTALL LAVATORY	Improve		EA.	1	Contractors	Safety Standards	\$1,000	
P12		OFFICE T35	Required	185.710, IPC 890.1130.f)3)	MISSING BACKFLOW PREVENTER AT ICE MAKER	INSTALL BACKFLOW PREVENTER IN WATER CONNECTION TO ICE MAKER	Improve		EA.	1	Contractors	Safety Standards	\$500	
P17		TOILET T36	Required	185.710, IPC 890.120	MISSING LAVATORY IN RESTROOM	INSTALL LAVATORY	Improve		EA.	1	Contractors	Safety Standards	\$1,000	
P15		OFFICE T35	Required	185.710, IPC 890.1010	ICE MAKER DRAIN IMPROPERLY INSTALLED	INSTALL TRAPPED AND VENTED INDIRECT WASTE CONNECTION	Improve		EA.	1	Contractors	Safety Standards	\$750	
P12		MECH T19	Required	185.710, IPC 890.1130.f)3)	MISSING BACKFLOW PREVENTER AT CHEMICAL FEED PUMP	INSTALL BACKFLOW PREVENTER IN WATER CONNECTION TO CHEMICAL FEED PUMPS	Improve		EA.	1	Contractors	Safety Standards	\$500	
FP1		CORRIDOR C008B	Required	175.450.a), NFPA 13	SPRINKLERS MISSING ON EAST SIDE OF CORRIDOR AT RAMPS	PROVIDE SPRINKLERS CONNECTED TO EXISTING SPRINKLER ZONE THREE WEST	Improve		L.S.	1	Contractors	Safety Standards	\$3,000	
FP4		MECH B21A	Required	175.450.a), NFPA 13, ART. 25.5	MISSING SIGNAGE AT FP RISERS	PROVIDE SIGN INDICATING AREA SERVED BY EACH CONTROL VALVE	Improve		EA.	1	Contractors	Safety Standards	\$500	
FP4		BOILER ROOM B24	Required	185.395.b).4).A), NFPA 13, ART. 25.5	MISSING SIGNAGE AT FP RISERS	PROVIDE SIGN INDICATING AREA SERVED BY EACH CONTROL VALVE	Improve		EA.	1	Contractors	Safety Standards	\$500	
FP5		STAIR S19	Required	185.395.4).d), NFPA 13	SPRINKLERS ARE CONNECTED TO DOMESTIC WATER PIPING AND DO NOT HAVE ISOLATION VALVES OR FLOW SWITCHES	INSTALL NEW SPRINKLERS CONNECTED TO EXISTING SPRINKLER ZONE 1 SYSTEM	Improve		EA.	2	Contractors	Safety Standards	\$1,000	
FP5		STAIR S20	Required	185.395.4).d), NFPA 13	SPRINKLERS ARE CONNECTED TO DOMESTIC WATER PIPING AND DO NOT HAVE ISOLATION VALVES OR FLOW SWITCHES	INSTALL NEW SPRINKLERS CONNECTED TO EXISTING SPRINKLER ZONE 1 SYSTEM	Improve		EA.	2	Contractors	Safety Standards	\$1,000	
FIRST FLOOR:														
P36		FOODS 131	Required	185.440.b).2)	MISSING EMERGENCY GAS SHUT-OFF IN PIPING TO RANGES	INSTALL EMERGENCY FUEL SHUT-OFF SWITCH	Improve		EA.	1	Contractors	Safety Standards	\$750	
P21		TOILET 147A	Required	185.710, IPC 890.680.c)	SELF-CLOSING LAV FAUCETS DO NOT PROVIDE PROPER FLOW OF WATER FOR JUVENILE HAND WASHING	INSTALL MIXING FAUCET ON LAVATORY	Improve		EA.	1	Contractors	Safety Standards	\$500	
FP3		CHORUS ROOM W02 (EXTERIOR)	Required	NFPA 13, ART. 8.17.2.4.5	FIRE DEPT. CONNECTION REQUIRES ADDITIONAL SIGNAGE	PROVIDE SIGN INDICATING AREA SERVED BY EACH FIRE DEPT. CONNECTION	Improve		EA.	1	Contractors	Safety Standards	\$500	
FP3		GREEN ROOM 101 (EXTERIOR)	Required	NFPA 13, ART. 8.17.2.4.5	FIRE DEPT. CONNECTION REQUIRES ADDITIONAL SIGNAGE	PROVIDE SIGN INDICATING AREA SERVED BY EACH FIRE DEPT. CONNECTION	Improve		EA.	1	Contractors	Safety Standards	\$500	

P18	MEN'S TOILET 209	Required	2009 IBC, IPC 890.680.e)	MISSING THERMOSTATIC MIXING VALVE ON LAVATORY	PROVIDE POINT OF USE THERMOSTATIC MIXING VALVE	Improve		EA.	1	Contractors	Safety Standards	\$300		

Priority Code	Action ID	Labor Code	Work Type
Urgent	Abandon in Place	District Employees	Safety Standards
Required	Remove	Contractors	Energy Conservation
Recommended	Repair		Handicapped Access
	Relocate		School Security
	Rebuild		Asbestos Treatment
	Improve		Paving Improvements
			Replacements
			Other Improvements

INSTRUCTIONS FOR TEN-YEAR SAFETY VIOLATION AND RECOM

1. **COUNTY CODE/NAME.** Enter the county name and the 3 digit county code for *School Districts and other Education Units.*
2. **DISTRICT CODE/NAME.** Enter district name and the 4-digit district number for *School Districts and other Education Units.*
3. **SITE CODE.** Enter the 3-digit number assigned by the Regional Superintendent.
4. **FACILITY CODE/NAME.** Enter the name of the building or site and the name of the SUPERINTENDENT.
5. **ITEM I.D.** Enter the number to identify the violation found during the inspection.
6. **LOCATION(S).** Specify the location(s) where the violation is found.
7. **PRIORITY CODE.** Enter the priority that best describes the degree of hazard.
 - a. Urgent identify items that present an immediate hazard to the safe use of the building. These items must be corrected within one year.
 - b. Required identify items that are necessary for a safe environment. Reference specific rules in the code that are applicable to the building.
 - c. Recommended identify items that do not present any immediate hazard. Reference specific rules in the code that are applicable to the building as authorized by ILCS 5/17-2.11. These include *energy conservation; security; repair of school sidewalks, playgrounds, etc.*
8. **RULE VIOLATED.** Specify the rule number in the code that is applicable. *Example: Fire alarm systems are not functioning properly - specify the year when the building was built.*
9. **DESCRIPTION OF VIOLATION** In a clear and concise manner, describe the violation.
10. **RECOMMENDATION TO CORRECT VIOLATION.** Describe the corrective action to be taken.

Funding Type

Fire Prevention

Other Funds

FOR COMPLETING YOUR SURVEY REPORT RECOMMENDATION SCHEDULE

County number taken from the *ISBE Directory of Illinois Public Schools, Public*

School number taken from the *ISBE Directory of Illinois Public Schools, Public School*

Superintendent.

Structure and the 3-digit facility number assigned by the REGIONAL

Inspection.

Hazard the problem creates:

Number of students and reference specific rules in the code that are applicable to

items that present less of an immediate hazard to the safety of students and staff. These items must be corrected within five years.

Hazard to the students and do not reference any specific rule in the code that these items are not required by code. Examples of recommended items are: *driveways, parking lots, or school bus turnarounds; and accessibility.*

Reference to the facility where the violation is found, as stated in Section 180.60, *section 185.395d, section 175.470 or section 918, the applicable rule used*

Describe the violation

Remedial measure to the rule violated in item 9 above.

