

Daily Log

Description

Taken Date

08/20/2026 at 11:27 am

Upload Date

08/20/2026 at 11:28 am

Uploaded By

John Burge

File Name

48DA70B5-F0B3-42D2-B...

Breaker boxes go
on the walls,
painter started
painting so boxes
can be installed on
top.



Daily Log

Description

Taken Date

08/20/2026 at 08:10 am

Upload Date

08/20/2026 at 08:11 am

Uploaded By

John Burge

File Name

1AB08798-264E-4C6B-8...

Roof Curbs for
Rooftop Units



Daily Log

Description

Taken Date

08/18/2026 at 02:13 pm

Upload Date

08/18/2026 at 02:18 pm

Uploaded By

John Burge

File Name

EF5325D6-F029-47C5-B...

**Air Barrier - South
Elevation of
Building**



Unclassified

Description

Taken Date

08/18/2026 at 12:19 pm

Upload Date

08/18/2026 at 12:22 pm

Uploaded By

Ryan Fuhler

File Name

92941AC5-68AC-48E4-9...

Janitor's Room



Unclassified

Description

Taken Date
08/18/2026 at 12:19 pm

Upload Date
08/18/2026 at 12:23 pm

Uploaded By
Ryan Fuhler

File Name
C520BD69-9264-4DB8-...
**Janitor's Room &
Varsity Locker
Room**



Unclassified

Description

Taken Date
08/17/2026 at 01:32 pm

Uploaded By
John Burge

File Name
B886C1C4-A32F-4743-A...
Men's Restroom



Aug 17, 2026 at 12:46:32PM CDT

Unclassified

Description

Taken Date
08/14/2026 at 02:27 pm

Upload Date
08/14/2026 at 02:27 pm

Uploaded By
Jeremy Durbin

File Name
[D970307A-1AB7-4038-8...](#)
**South Elevation
with Concession
Windows**



Unclassified

Description

Taken Date
08/14/2026 at 02:27 pm

Upload Date
08/14/2026 at 02:27 pm

Uploaded By
Jeremy Durbin

File Name
[1BAB9A71-EC22-44D6-B...](#)
Concession Stand

