

*SPS BOND 2023
PROJECTS REPORT
11.11.2025*



HS Phase 1 and 2 – Construction Phase

- Owner, Architect, and Constructor (OAC) meetings are scheduled for every two weeks to review construction progress and coordination with upcoming installations of SPS Owner provided equipment and systems.
- SPS FF&E Procurement is progressing.

HS Phase 1 and 2 – Construction Phase

SITE WORK SUMMARY

- West parking lot paving is in progress.
- Landscaping (trees/sod/irrigation)
West and East side is in progress



HS Phase 1 and 2 – Construction Phase



OCTOBER 29, 2025




OCTOBER 6, 2025



HS Phase 1 and 2 – Construction Phase




EXTERIOR – ENTRY LANE ISLAND TREES AND BOULDERS



HS Phase 1 and 2 – Construction Phase




EXTERIOR – WEST PARKING / DROP-OFF LANE



HS Phase 1 and 2 – Construction Phase

AREA 1 WORK SUMMARY


- Millwork installation is complete
- Door hardware installation is complete
- Corridor ceiling grid is complete
- Exposed structure painting is complete
- MEP trim out is in progress
- Science Lab Fume hood installation is in progress.



HS Phase 1 and 2 – Construction Phase




AREA 1 – COMMON SPACE



HS Phase 1 and 2 – Construction Phase




AREA 1 – SCIENCE HALLWAY



HS Phase 1 and 2 – Construction Phase




AREA 1 – SCIENCE HALLWAY



HS Phase 1 and 2 – Construction Phase




AREA 1 – SCIENCE LAB



HS Phase 1 and 2 – Construction Phase




AREA 1 – NORTH STAIRWAY



HS Phase 1 and 2 – Construction Phase

AREA 2 WORK SUMMARY


- Plumbing fixture installation is complete
- Light fixture installation is complete
- Millwork installation is complete.
- Corridor ceiling grid is in progress.
- Locker installation is in progress.
- Metal panel installation is in progress.



HS Phase 1 and 2 – Construction Phase




AREA 2 – EXTERIOR METAL PANELS



HS Phase 1 and 2 – Construction Phase

AREA 3 WORK SUMMARY


- Light fixture installation is complete.
- Millwork installation is in progress.
- Wall tile installation is complete
- Greenhouse installation is complete



HS Phase 1 and 2 – Construction Phase




AREA 3 – CONNECTION TO STUDENT CENTER



HS Phase 1 and 2 – Construction Phase




AREA 3 – PRESENTATION ROOM ENTRY



HS Phase 1 and 2 – Construction Phase




AREA 3 – GIRLS RESTROOMS



HS Phase 1 and 2 – Construction Phase

AREA 4 WORK SUMMARY


- Fiber cement panels are nearing completion.
- Exterior curtain walls are in progress.
- Hard lid drywall ceilings are in progress.
- Tape, bed, prime and first coat of paint in progress
- Restroom tile is complete.
- Polycarbonate canopy panels are in progress



HS Phase 1 and 2 – Construction Phase




AREA 4 – BUILDING ENTRY



HS Phase 1 and 2 – Construction Phase




AREA 4 – ADMIN / PATIO CANOPY



HS Phase 1 and 2 – Construction Phase




AREA 4 – ENTRY LOBBY



HS Phase 1 and 2 – Construction Phase




AREA 4 – PIONEER PERCH / STUDENT CENTER



HS Phase 1 and 2 – Construction Phase




AREA 4 – STUDENT CENTER




HS Phase 1 and 2 – Construction Phase




AREA 4 – MEDIA CENTER VIEW TO PATIO



HS Phase 1 and 2 – Construction Phase




AREA 4 – MEDIA CENTER



HS Phase 1 and 2 – Construction Phase




AREA 4 – MEDIA CENTER ENTRY AREA



HS Phase 1 and 2 – Construction Phase




AREA 4 – MEDIA CENTER PATIO



HS Phase 1 and 2 – Construction Phase

AREA 5 WORK SUMMARY


- Tape, bed, prime and first coat of paint in progress
- 2nd floor ceiling grid is in progress.
- Overhead MEP rough-in is nearing completion.
- Kitchen MEP rough-in is in progress.



HS Phase 1 and 2 – Construction Phase




AREA 5 – KITCHEN FRAMING



HS Phase 1 and 2 – Construction Phase




AREA 5 – ELA HALLWAY



HS Phase 1 and 2 – Construction Phase

AREA 6 SUMMARY


- Exposed structure painting is in progress.
- Acoustical ceiling installation is in progress.
- Hard lid drywall ceilings are in progress.
- Restroom tile is in progress.
- Overhead MEP is nearing completion.
- Misc soffit framing is in progress.
- Tape, bed, prime, and 1st coat of paint is in progress.
- Curtain walls have been installed.



HS Phase 1 and 2 – Construction Phase




AREA 6 – CHOIR CLASSROOM



HS Phase 1 and 2 – Construction Phase




AREA 6 – PA WING RESTROOMS



HS Phase 1 and 2 – Construction Phase




AREA 6 – PA WING LARGE BAND ROOM




HS Phase 1 and 2 – Construction Phase




AREA 6 – PA WING PRACTICE ROOMS / COMMON SPACE



HS Phase 1 and 2 – Construction Phase



AREA 6 – PA WING COMMON SPACE



HS Athletics Phase 1 Design Phase

SPS Athletics Phase 1 improvements on the existing High School campus that include new gym, weight room, wrestling, locker rooms, indoor practice spaces, outdoor practice field, and associated supports spaces. Project is in Design Development Phase.

- SPS Athletics Phase 1 KUG Design Development review meetings are on going for the individual spaces.
- Design Development 50% KUG and DRC Second meeting and Community Meetings are upcoming on 12/1.
- SPS Athletics Phase 1 is scheduled to Bid in April 2026 and begin construction in June 2026.





STILLWATER PUBLIC SCHOOLS

